

NOTICES TO MARINERS

Issue No.16(Total No.1071)

Notice No.405-414

18 April 2022

CONTENTS

I Sailing Bulletin

 $lap{I}$ Index

■ Notices to Mariners

IV Temporary Notices

In order to keep navigation safety and make Chinese coastal port and fairway Charts modify timely and accurately, mariners are requested to inform the china MSA immediately of the discovery of new danger, or changes or defects in aids to navigation and of shortcomings in Chinese coastal port and fairway charts or publications. Copies of Navigational warning, Sailing information, and Dynamic aids condition should be sent to Tianjin, Shanghai and Guangdong MSA timely. Departments and mariners may contact Shanghai Marine Chart Press Center or Tianjin, Shanghai and Guangdong MSA to get subscribing information. The Notices to Mariners can also be made through the following websites.

In addition to postal methods, the following additional communication facilities are available:

Tianjin MSA Survey and Mapping Office: E-mail: hcdd@tjmsa.gov.cn

Phone: +86(0)22 58873986 Fax: +86(0)22 58873988

Shanghai Marine Chart Press Center: E-mail: gztg@shchart.cn

Phone: +86(0)21 65806556 Fax: +86(0)21 65697997

Guangdong MSA Survey and Mapping Office: E-mail: hcmail@gdmsa.gov.cn

Phone: +86(0)20 89320335 Fax: +86(0)20 89320336

China MSA Nautical Charts&Books Publisher: Web: www.chart.msa.gov.cn

The Maritime Safety Administration of the People's Republic of China

Explanatory Notes

- 1. The Notices which publish the information about essential changing feature of Chinese coastal sea area and works at sea, is mainly used to correct the Chinese coastal port and fairway Charts and offer navigation safety information for mariners.
- 2. The information published in the notice origins from the marine information, the navigational warning, aids dynamics as well as the hydrographic achievements, which are issued by Maritime Administration. The additional source comes from shipping, fairway, sea, Harbour affairs, and fishing politics department.
- 3. The Notices include the Sailing Bulletin, the Notices to Mariners and Temporary Notices.
 - a) Sailing Bulletin announces rules and regulations of navigation, the printing, correcting and cancellation of publication, and the marine information which is promulgate by MSA and has important relationship which navigation safety. It is not used to correct the Charts.
 - b) The Notices to Mariners is used for user to correct related Chinese coastal port and fairway Charts. The number in parentheses behind the Chart No. indicates that only parts of the Notices related to this chart. The number in square bracket illustrated the previous update notice information.
 - c) The Temporary Notices published for the temporary establishment, cancellation, variation as well as works at sea. The Chart No. lists for user's convenience when mariners look up for the details.
- 4. Geographical position refer to the horizontal datum of the current edition of each affected chart. The sounding datum refers to the level of Lowest Astronomical Tide and the elevation uses 1985 national vertical datum. Bearings are true reckoned clockwise from 000° to 359°. Those relating to lights are from seaward. The height of the lighthouse or light beacon is referred to Mean High Water Springs.
- 5. For symbols used in the Notices to Mariners, see GB12319–1998.
- 6. The unit in the Notices complies with the international standard unit of measurement, with the Chinese characters replaced by symbol and alphabet, such as degrees (°), minutes (′) and seconds (″), meters (m), kilometers (km) or nautical miles (M).

SAILING BULLETIN

1, Publication Information

1.New Chart Information

No.	Chart No.	Name	Scale	Date	Note
1	44127	NANCAO FAIRWAY (I)	1:25 000	2022年3月第41版	
2	44128	NANCAO FAIRWAY (II)	1:25 000	2022年3月第41版	
3	44129	NANCAO FAIRWAY (III)	1:25 000	2022年3月第41版	

2.Disused Chart Information

No.	Chart No.	Name	Scale	Date	Note
1	44127	NANCAO FAIRWAY (I)	1:25 000	2021年12月第40版	
2	44128	NANCAO FAIRWAY (II)	1:25 000	2021年12月第40版	
3	44129	NANCAO FAIRWAY (III)	1:25 000	2021年12月第40版	

2, Marine Information

1. Chinese Version Only.

Source Yantai Navigation Notice 117/2022

· 1 ·

INDEX

1,GEOGRAPHICAL INDEX

Bohai Sea	Suizhong Port Northeastwards (405)	
	Dongying Port	(409),(410)
	West of Dongying Port	(411),(412)
	Dongying Port Eastwards	(406)
	Approaches to Dongying Port	(413)
Yellow Sea	Rizhao Port	(414)
East China Sea	Changijangkou and Approaches (407),(408)	

2,INDEX OF CHARTS AFFECTED

Chart No.	Notice No.	Notice No. (T)
21001	405	
33001		413
37123		414
1303	405	
1304	406	409、410、411、412
44001	407、408	
44122	407	
44125	408	
44126	408	
44173	407	
44174	408	
2308	407	

Notices to Mariners

405.Bohai Sea - Suizhong Port Northeastwards - V-AIS

Insert (*) V-AIS 40°09′33″.3N,120°20′27″.1E

Chart 21001(2021-1347) 1303(2022-321)

List of Lights CNP81/2021~2022[1610655]

Source Beihai Aids 014/2022

406.Bohai Sea - Dongying Port Eastwards - Buoyage

Insert $\sqrt{\frac{N(2)5s}{N(2)5s}}$ 38°01′28″.6N,119°22′14″.5E

Chart 1304[2022-349]

List of Lights CNP81/2021~2022[3110241.061]

Source Beihai Aids 013/2022

407. East China Sea - Changjiangkou and Approaches - Obstruction

Delete 2₅ (1)31°08′44″.6N,122°15′13″.9E

2₅ 及等深线 (2)position (1) above

Insert 概位 0, 据报 (3)31°05′44″.4N.122°15′13″.2E

0. 及等深线 (4)position (3) above

Chart 44001(2;4)(2022-352) 44122(1;3)(2021-) 44173(1;3)(2022-352)

2308(4)[2022-353]

Source Shanghai Navigation Warning 0215/2022

408.East China Sea - Changjiangkou and Approaches - Wreck

Insert 概位: 据报(2022) 31°25′18″.0N,121°31′06″.6E

Note: The wreck is 56m long.

Chart 44001(2022-407) 44125(2022-74) 44126(2021-) 44174(2022-352)

Source Shanghai Navigation Warning 0210/2022

Temporary Notices

409.Bohai Sea - Dongying Port - Construction (T)

Date March 11 to December 30, 2022

Area joining: (1)38°17′00″.0N,118°48′23″.0E

(2)38°15′39″.0N,118°52′08″.0E (3)38°10′59″.0N,118°50′31″.0E (4)38°13′31″.0N.118°46′26″.0E

(5) ... (1) 1

(5)position (1) above

Chart 1304

Source Dongying Navigation Notice 122/2022

410.Bohai Sea - Dongying Port - Construction(T)

Date March 11 to December 30, 2022

Area joining: (1)38°15′55″.0N,118°57′49″.0E

(2)38°09′47″.0N,118°57′35″.0E (3)38°09′32″.0N,118°55′49″.0E

(4)38°11′46″.0N,118°54′42″.0E

(5) position (1) above

Chart 1304

Source Dongying Navigation Notice 123/2022

411.Bohai Sea - West of Dongying Port - Drilling(T)

Date March 15 to September 30, 2022

Area radius 500m, central point: 38°12′50″.4N,118°48′03″.3E

Chart 1304

Source Dongying Navigation Notice 124/2022

412.Bohai Sea – West of Dongying Port – Drilling (T)

Date March 20 to September 30, 2022

Area radius 500m, central point: 38°12′42″.4N,118°48′24″.0E

Chart 1304

Source Dongying Navigation Notice 125/2022

Blank Page

413.Bohai Sea – Approaches to Dongying Port – Construction (T)

Date March 15 to December 31, 2022

Area 1, radius 1M, central point: (1)37°50′35.8″N,119°41′27.0″E

Area 2, radius 1M, central point: (2)37°50′12.9″N,119°35′23.0″E

Area 3, radius 1M, central point: (3)37°48′39.6″N,119°37′30.0″E

Note: Unrelated ships are not allowed to enter the temporary safety operation area.

Chart 33001

Source Yantai Navigation Notice 131/2022

414. Yellow Sea - Rizhao Port - Lanshan Harbour - Dredging (T)

Date March 9 to August 31, 2022

Area joining: (1)35°06′12″.4N,119°23′15″.7E

(2)35°05′41″.3N,119°23′38″.3E

(3)35°05′09″.5N,119°23′51″.5E

(4)35°05′13″.9N,119°23′58″.6E

(5)35°06′00″.4N,119°23′39″.7E

(6)35°06′18″.3N,119°23′37″.0E

(7)position (1) above

Note: Keep watching on VHF Ch.16&09.

Chart 37123

Source Rizhao Navigation Notice 115/2022

Blank Page

HYDROGRAPHIC INFORMATION REPORT SHEET

Name(s)of report sender(s)
Mailing address
Subject
Geograghical area
Position or area limit("PA"indicated if applicable)
Affected chart(s)/publication(s)
Details:
Suggestion(s)/request(s)

Signature:

Date:

HYDROGRAPHIC INFORMATION REPORT SHEET INSTRUCTIONS

1. Extent of Information to be reported:

- a) Discovery or the changes in position, range, depth of uncovered reefs, shoals, wrecks or other obstructions.
- b) Discovery or changes of floating objects (e.g buoys, mooring buoys, large scale fishing stakes, floating shipwrecks), magnetic anomalies, discolored water or breakers.
 - c) Establishments or changes of navigation facilities.
- d) Establishments or changes of mooring or berthing facilities (e.g. piers, submarine cables, overhead cables, mooring buoys, breakwaters).
 - e) Changes in the limit of fairway, anchorages or sailing route.
 - f) Shortcomings in Chinese coastal port and fairway charts and other relative publications.

2. Instructions:

- a) Measuring instrument, methods and time should be specified in expressing the location or scope; and the coordinate system should be indicated (1954 Beijing coordinate system or WGS-84 coordinate system).
- b) When position expressed in bearing and distance, the origin should be specified; and when position expressed in latitude and longitude, the number, edition and publisher of chart referred to should be specified.
- c) Measuring instrument, methods and time of the obstruction or shoal soundings should be indicated. In addition, the sounding datum and whether it makes corrections for the height of the tide should also be indicated.
- d) Elevation of a navigational mark should be accompanied by the datum it referred to, and height of a light should indicate whether it refers to that of the top or that of the center.
 - e) The report should be signed and affix the official seal.

3. Remarks:

- a) The information reported will be checked upon our receipt and then used to the best advantage which may mean inclusion in due weekly edition of Notices to Mariners. Certain amount of compensation will be given to the report senders.
- b) Please send the report to Shanghai MSA Survey and Mapping Office. Address: 82 Lane 7, Gongqing Road, Yangpu District, Shanghai.